

Basic Construction Draw Inspection - Single

Customer Info

Account Number: 2311-01343

Company Name: Member First Mortgage LLC

Contact Name: Sandee Harvey-McCullough and
James McCullough

Address: 131 McKenzie Road,
Milner, GA 30257, USA

Job Order Info

Job Order ID: 10099273

Date Assigned: 11/21/2023

Date Completed: 11/27/2023

GENERAL OBSERVATIONS

% of Work Completed

100

Date Inspected

11/27/2023



Additional Comments on Work Completed

Roof, clearing and padding, temp power pole, temp driveway, framing materials have been used, Slab materials have been used, roof has been installed, insulation has been installed and roughed electrical/plumbing/ HVAC has been completed.

% of Work Remaining

0

Additional Comments on Work Remaining

All work on the draw has been completed in a workmanlike manner.

INSPECTOR SIGNATURE AND COMPLETION DATE

Signature

Nicole Simons

Printed Name

Nicole Simons

Completion Date

11/27/2023





Cover Photo - Front View

Location: 33.119703, -84.203722

Date: Nov 27, 2023 01:36:59 PM EST

Address: 131 McKenzie Road Milner, GA 30257


Inspection completed by Incenter Appraisal Management
For any additional information feel free to call (704) 569-5048
or email IAM@incenterms.com



Aerial View

Location: 33.119695, -84.203722
Date: Nov 27, 2023 01:36:14 PM EST

Aerial View



Map View

Location: 33.119695, -84.203722
Date: Nov 27, 2023 01:36:14 PM EST

Map View



HVAC

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:46:12 PM EST

HVAC



Left Side View

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:38:47 PM EST

Left Side View



Temp power pole
Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:41:15 PM EST



Temp driveway
Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:43:31 PM EST



Temp driveway
Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:43:40 PM EST



Clearing
Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:43:59 PM EST



Clearing

Location: 33.120075, -84.203684

Date: Nov 27, 2023 01:44:05 PM EST



Clearing

Location: 33.120075, -84.203684

Date: Nov 27, 2023 01:44:17 PM EST



Slab Concrete

Location: 33.120075, -84.203684

Date: Nov 27, 2023 01:45:10 PM EST



Framing

Location: 33.120075, -84.203684

Date: Nov 27, 2023 01:45:29 PM EST



Framing

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:45:41 PM EST



Electrical

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:46:36 PM EST



Plumbing

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:47:15 PM EST



Plumbing

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:47:28 PM EST



Insulation

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:47:53 PM EST



Spray Foam

Location: 33.120075, -84.203684
Date: Nov 27, 2023 01:48:25 PM EST



Rear View

Location: 33.120093, -84.203691
Date: Nov 27, 2023 01:38:17 PM EST

Rear View



Right Side View

Location: 33.119703, -84.203722
Date: Nov 27, 2023 01:37:25 PM EST

Right Side View